Please complete every section daily and give to at ENV Station 001.

Date: <u>7-46-1</u>

lime: 1030

Answers
Y / (R)
/3 (1)

Date: 9-26-17
Time: 1/00
Initials: K)(

Outfall 001	Answers
Substance discharged?	Y / (N)
-If Yes, Color?	
-If Yes, Size / Area?	
Vac truck amount recovered	
Estimated oil recovered	***************************************
Length of sorbent boom replaced	~200H
Canal Appearance (winds, sheen, etc.)	17 54/